Declassified in Part - Sanitized Copy Approved for Release 2012/06/12 : CIA-RDP78-03424A000500100029-6

Office Memorandum • United States Government

33	\cdot	
то :	The Files - RD-76, Task Order I	
FROM:		25X1
subject:	(Conference Report - Time Event Marker, IN-7)	
	1. On 22 January 1960 a meeting was held with in Alcott Hall, Washington, D. C. The purpose of this meeting was to	25X1 25X1
	discuss the progress of the subject task. The Agency personnel present were:	25X1
	very well and they should be able to produce them with very little trouble.	25X1 25X1 25X1
- 224 15 944	REV DATE 0 1980 BY 077 933 OPI 56 TYPE 02 S PAGES 2 REV CLASS C NEXT REV 20/0 AUTH: HR 70-2	

Declassified in Part - Sanitized Copy Approved for Release 2012/06/12 : CIA-RDP78-03424A000500100029-6

برا، دنسه ب

SUBJECT: Conference Report - Time Event Marker, IN-7

He also stated that prior to the initiation of this task had made recommendation against building quantities of the IN-7 until after the design of a ruggedized unit was completed because of expected problems. Also, that the Agency insisted on the approach to fabricate 15 units whether they work or not. It is hardly considered possible or probable by this writer that any statements made by Agency personnel could have been misconstrued to this interpretation.

The evaluation of the ruggedized model of the IN-7 was next discussed with During this evaluation three failures have occurred, the last of which has made further evaluation impossible without rework. A cursory examination of the unit was made and it was determined that a momentary grounding, either internal or external to the unit, of the sweep readout line had caused burn out of a set of bridging contacts in the sweep readout circuit by placing them directly across the battery. Methods of providing protection to these fine wire contacts were discussed: however. a solution was not decided on until the contractor can further investigate. The possible cause of failures encountered during the low temperature tests was discussed. The contractor felt that this may have been caused by the differences in power sources used during testing. This is due to the nature of the equipment which requires varying current pulses depending on the number of functions occurring in the unit at the instant of current pulse demand. Therefore, the voltage of the battery source we used may have dropped below the voltage for proper operation of the unit under low temperature testing. They had used a regulated power supply during their testing phase. We expressed our concern that, although this method may be all right for testing, we will have to have recommended maximum current pulse demands expected during operation over extremes of the environmental specifications so that proper selection of battery supplies can be made.

4. It was decided that the ruggedized unit would be returned to the contractor for further examination to ascertain the cause of these troubles and rework for the correction thereof. The contractor will submit a request for a time extension and more funds for this additional work.

25X1

25X1

25X1

25X1

Distribution:

R+D Subject File
R+D Lab
OC-SP/EA
Monthly (2)
EP Chrono

CONFIDENTIAL

- 2 -